Date:	Property is: Single Fan 8/25/2010	nily X Duplex	Other		
ake no respo	nsibility for problems discovered	after the inspection da	s. The City of Milwaukee, the Redevelopment Authority, a te, or for omissions through error or oversight. The list do leral Block Grant or HOME programs.		
Exterior (	Condition Report				
Location Site	Required Work Landscaping	n/a Yes X	Note/Comments Increase grade, trimming	\$	<b>Cost</b> 600.00
Site	Steps/Handrails	n/a X Yes	merease grade, imming	 \$	000.00
	Service walks	n/a X Yes		\$	
	Fencing	n/a X Yes		\$	
	Parking	n/a X Yes		\$	
	Retaining walls	n/a X Yes		\$	
	Other	n/a X Yes		\$	
	Other	n/a X Yes		\$	
Garage	Shingles: repair	n/a X Yes		\$	
	Shingles: Roof over existing	n/a X Yes		\$	
	Shingles:Tear off & re-roof	n/a Yes X	Roof boards damaged, tear off and replace shingles	**************************************	3,500.00
	Gutters/downspouts	n/a X Yes		\$	,
	Flashing	n/a X Yes		\$	
	Eaves	n/a X Yes		\$	
	Siding	n/a X Yes		\$	
	Doors	n/a X Yes		\$	
	Windows	n/a X Yes		\$	
	Slab	n/a X Yes		\$	
	Paint	n/a X Yes		\$	
	Electrical	n/a X Yes		\$	
	Other	n/a Yes		\$	
Porches	Roof	n/a X Yes		\$	
	Deck-upper	n/a X Yes		\$	
	Decklower	n/a X Yes		\$	
	Steps/handrails	n/a Yes X	Front wood steps missing handrail	\$	350.00
	Ceiling	n/a Yes X	Front porch ceiling damaged/leaking	\$	750.00
	Guardrails	n/a X Yes		\$	
	Structural	n/a X Yes		\$	
	Paint	n/a X Yes		\$	

Other

n/a Yes

\$

## House

Chimney	n/a X Yes	\$ 
Shingles: repair	n/a X Yes	\$
Shingles: Roof over existing	n/a X Yes	\$ 
Shingles:Tear off & re-roof	n/a Yes X Tear off and replace shingles	\$ 8,000.00
Gutters/downspouts	n/a Yes X Replace gutters/downspouts	\$ 1,100.00
Flashing	n/a X Yes	\$ 
Eaves	n/a X Yes	\$ 
Siding	n/a X Yes	\$ 
Storm Doors	n/a X Yes	\$ 
Prime ("main") Doors	n/a X Yes	\$ 
Storm Windows	n/a Yes X Replace front storm door	\$ 350.00
Prime ("main") Windows	n/a X Yes	\$ 
Paint	n/a X Yes	\$ 
Foundation	n/a X Yes	\$ 
Electrical	n/a X Yes	\$ 
Other	n/a Yes	\$ 
Other	n/a Yes	\$ 
Other	n/a Yes	\$ 
Other	n/a Yes	\$

Exterior: Estimated Cost:\*

14,650.00

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.

interior Co	onaition Report			_	
	, -	X		Lower unit of duplex	
Maahaniaal	Upper unit of duplex Required Work			Other	
Heating	nequired work				
ricumig	Repair/replace boiler	n/a X	Yes	]	\$
	Repair radiation	n/a X	Yes	]	\$ 
	Repair/replace furnace	n/a	Yes X	Replace furnace	\$ 4,000.00
	Repair ductwork	n/a	Yes X	Areas of ductwork rusted	\$ 600.00
	Replace thermostat	n/a X	Yes	]	\$
	Repair/replace grilles	n/a X	Yes	]	\$
	Tune boiler/furn. insp ht exchange	n/a X	Yes		\$
Electrical	Repair/replace receptacles	n/a X	Yes	]	\$
	Repair/replace switches	n/a X	Yes	]	\$
	Repair/replace fixtures	n/a X	Yes	]	\$
	Install outlets and circuits	n/a X	Yes	]	\$
	Install outlets and circuits	n/a X	Yes	]	\$
	Install outlets and circuits	n/a X	Yes	]	\$
	Install outlets and circuits	n/a X	Yes	]	\$
	Upgrade service	n/a X	Yes	]	\$
	Other	n/a	Yes	]	\$
	Other	n/a	Yes	]	\$
Plumbing		_ <del>_</del>		1	
	Repair/replace kitchen sink	n/a	Yes X	Replace	\$ 550.00
	Repair/replace kitchen sink fauce	n/a	Yes X	Replace	\$ 150.00
	Repair/replace tub	n/a	Yes X	Replace	\$ 650.00
	Repair/replace tub faucet	n/a	Yes X	Replace	\$ 150.00
	Repair/replace toilet	n/a	Yes X	Replace	\$ 350.00
	Repair/replace lavatory	n/a	Yes X	Replace	\$ 400.00
	Repair/replace lavatory faucet	n/a	Yes X	Replace	\$ 150.00
	Repair/replace wash tub	n/a X	Yes	]	\$
	Repair/replace wash tub faucet	n/a X	Yes	]	\$
	Unclog piping:	n/a X	Yes	]	\$
	Repair drain/waste/vent piping	n/a X	Yes	]	\$
	Repair water piping	n/a	Yes X	Several areas damaged/leaking	\$ 900.00
	Repair/replace water heater	n/a X	Yes		\$
	Other	n/a	Yes	]	\$

\$

n/a Yes

Other

Windows					
	Replace broken glass	n/a Yes	X	Several broken glass	\$ 750.00
	Repair or replace sash	n/a Yes	Χ	Multiple need replacing	\$ 3,500.00
Doors	Repair or replace doors	n/a Yes	Х	Several doors damaged/missing	\$ 1,200.00
	Repair or repl. locks/latches	n/a Yes	X	Several missing	\$ 300.00
Walls/Ceilin	gs Repair or repl. @ defective	n/a Yes	Х	Several areas drywall damaged	\$ 1,500.00
Paint	Repair or repl. @ defective	n/a Yes	Х	Several rooms need fresh paint	\$ 600.00
Fire Safety	Install smoke alarm:bsmt.	n/a Yes	X	Self Help	\$ 75.00
	Install smoke alarm: 1st flr.	n/a Yes		Self Help	\$ 75.00
Handrails	Install smoke alarm: 2nd flr.	n/a Yes	Χ	Self Help	\$ 75.00
i iaiiui aiis	Repair/replace defective	n/a Yes	X	Missing handrail to 2nd floor	\$ 150.00
Stairs	Repair defective	n/a X Yes			\$
Floors	Repair defective	n/a Yes	Х	Several floors need new coverings	\$ 2,200.00
Other		n/a Yes	X	Basement mold apparent	\$ 1,250.00
		n/a Yes			\$
		n/a Yes			\$
		n/a Yes			\$
				Interior: Estimated Cost:	\$ 19,575.00
				Total Exterior and Interior Cost:*	\$ 34,225.00

Prepared by: Jeff Moser, Advantage Home Inspection Services Date: 8/25/2010

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.